

**\*TCM Calibration\***



**Step 2:**  
**StarFire**

**Step 3:** Select the Setup Tab at the top of the Screen.




**Step 1:**

Select **Main Menu**

**Step 4:** Select the "Cal" button.

**\*Note:** If you do not see the Setup Tab, press the StarFire or "F" Tab in the upper right hand corner.

**Step 5:** Once you see this screen, follow the directions provided.



**\*Note:** John Deere Recommends that a TCM Calibration be done every day.

**\*Note:** Adaptive Curves is based off of Pass to Pass Accuracy. Therefore, you will have to drive the first pass before a line is generated on the display.

**\*Adaptive Curve Setup\***



**Step 2:** Turn Adaptive Recording "On" by selecting the button to the left.

**\*Note:** When Recording is "On" the light shown to the left should be flashing Red.



**Step 1:** Select Adaptive Curves from the Tracking Mode box.



**Step 3:** Press the "Steer Off" button to turn the Steering On. Once you have done this, there should be 3 pieces of the pie.